

Appendix B. Setup Photographs

<Conducted Emission>



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIOCAM Page Number : B1 of B2
Report Issued Date : May 14, 2015
Report Version : Rev. 01


Report No.: FR532407B




<Radiated Emission>

Z Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIOCAM Page Number : B2 of B2
Report Issued Date : May 14, 2015
Report Version : Rev. 01

Report No.: FR532407B