3. Internal Photograph of EUT

Brand Name: BLU; Model Name: Studio 5.5 S; Marketing Name: Studio 5.5 S;

Report No.: EP3D1804



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO55S Page Number : 11 of 28
Report Issued Date : Jan. 13, 2014

Report Version : Rev. 01

Report No.: EP3D1804




TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO55S Page Number : 12 of 28
Report Issued Date : Jan. 13, 2014
Report Version : Rev. 01

Report No.: EP3D1804




TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO55S Page Number : 13 of 28
Report Issued Date : Jan. 13, 2014
Report Version : Rev. 01

Report No.: EP3D1804




TEL: 86-755-3320-2398 FCC ID: YHLBLUSTUDIO55S Page Number : 14 of 28
Report Issued Date : Jan. 13, 2014
Report Version : Rev. 01

Report No.: EP3D1804




TEL: 86-755-3320-2398 FCC ID: YHLBLUSTUDIO55S Page Number : 15 of 28
Report Issued Date : Jan. 13, 2014
Report Version : Rev. 01

Report No.: EP3D1804



TEL: 86-755-3320-2398 FCC ID: YHLBLUSTUDIO55S Page Number : 16 of 28
Report Issued Date : Jan. 13, 2014
Report Version : Rev. 01



0 to 20 to 30 to 3

Brand Name: BLU; Model Name: Studio 5.5 S; Marketing Name: Studio 5.5 S;

TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO55S Page Number : 17 of 28
Report Issued Date : Jan. 13, 2014
Report Version : Rev. 01



30

Brand Name: BLU; Model Name: Studio 5.5 S; Marketing Name: Studio 5.5 S;

Report No.: EP3D1804


SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: YHLBLUSTUDIO55S

: 18 of 28 Page Number Report Issued Date : Jan. 13, 2014 Report Version : Rev. 01


07

Report No.: EP3D1804




TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO55S Page Number : 19 of 28
Report Issued Date : Jan. 13, 2014
Report Version : Rev. 01

Report No.: EP3D1804




TEL: 86-755-3320-2398 FCC ID: YHLBLUSTUDIO55S Page Number : 20 of 28
Report Issued Date : Jan. 13, 2014
Report Version : Rev. 01

Report No.: EP3D1804



TEL: 86-755-3320-2398 FCC ID: YHLBLUSTUDIO55S Page Number : 21 of 28
Report Issued Date : Jan. 13, 2014
Report Version : Rev. 01


Report No.: EP3D1804



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO55S Page Number : 22 of 28
Report Issued Date : Jan. 13, 2014
Report Version : Rev. 01




Report No.: EP3D1804



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO55S Page Number : 23 of 28
Report Issued Date : Jan. 13, 2014
Report Version : Rev. 01




Report No.: EP3D1804



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO55S Page Number : 24 of 28
Report Issued Date : Jan. 13, 2014
Report Version : Rev. 01

Report No.: EP3D1804



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO55S Page Number : 25 of 28
Report Issued Date : Jan. 13, 2014
Report Version : Rev. 01

Report No.: EP3D1804




TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO55S Page Number : 26 of 28
Report Issued Date : Jan. 13, 2014
Report Version : Rev. 01

Report No.: EP3D1804



TEL: 86-755-3320-2398 FCC ID: YHLBLUSTUDIO55S Page Number : 27 of 28
Report Issued Date : Jan. 13, 2014
Report Version : Rev. 01

Report No.: EP3D1804



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO55S Page Number : 28 of 28
Report Issued Date : Jan. 13, 2014
Report Version : Rev. 01