


Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTX8HD Page Number : B1 of B2
Report Issued Date : Mar. 24, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 1.1


Report No.: FR622506A



<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTX8HD Page Number : B2 of B2
Report Issued Date : Mar. 24, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 1.1

Report No.: FR622506A