

### **Report No.: FA260505**

# Appendix D. Product Photos





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDECOXT Page Number : D1 of D2
Report Issued Date : Jun. 26, 2012
Report Version : Rev. 01



**Report No.: FA260505** 

#### **Antenna Location:**



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDECOXT Page Number : D2 of D2
Report Issued Date : Jun. 26, 2012
Report Version : Rev. 01




### **Report No. : FA260505**

# Appendix E. Test Setup Photos



**Right Cheek** 


**Right Tilted** 







**Left Tilted** 



Front of the DUT with Phantom 1.5 cm Gap



Back of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDECOXT Page Number : E1 of E1
Report Issued Date : Jun. 26, 2012
Report Version : Rev. 01