


Appendix B. Setup Photographs

<Conducted Emission>





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVOX Page Number : B1 of B2
Report Issued Date Nov. 29, 2017
Report Version : Rev. 01


Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR7O3102A




FCC RF Test Report

<Radiated Emission> Z Plane LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVOX Page Number : B2 of B2
Report Issued Date Nov. 29, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR7O3102A