
Appendix A. Setup Photographs

<Conducted Emission>

Mode 3



Mode 4



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTX8HD Page Number : A1 of A3
Report Issued Date : Mar. 24, 2016
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.3

Report No. : FC622506


<Radiated Emission>

Mode 3

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTX8HD Page Number : A2 of A3
Report Issued Date : Mar. 24, 2016
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.3

Report No. : FC622506


Report No. : FC622506

Mode 4

LF



HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTX8HD Page Number : A3 of A3
Report Issued Date : Mar. 24, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3