

**Report No. : FC411003** 


# Appendix A. Setup Photographs

## <Conducted Emission>

#### Mode 2



Mode 3



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: YHLBLUSTARJR Page Number : A1 of A3 Report Issued Date: May 04, 2014 Report Version : Rev. 01






### <Radiated Emission>

#### Mode 2

LF



HF



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTARJR Page Number : A2 of A3
Report Issued Date : May 04, 2014
Report Version : Rev. 01


Report No.: FC411003






Mode 3

LF



HF



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTARJR Page Number : A3 of A3
Report Issued Date : May 04, 2014
Report Version : Rev. 01

Report No.: FC411003