

Report No.: FA222201

Appendix D. Product Photos






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUCLICKLITE Page Number : D1 of D1
Report Issued Date : Mar. 05, 2012
Report Version : Rev. 01



Report No.: FA222201

Appendix E. **Test Setup Photos**






Right Cheek

Right Tilted





Left Cheek

Left Tilted





Face of the DUT with Earphone to Phantom 1.5 cm Gap



Bottom of the DUT with Earphone to Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUCLICKLITE Page Number : E1 of E1 Report Issued Date: Mar. 05, 2012 Report Version : Rev. 01