



Appendix B. Setup Photographs

<Radiated Emission>

LF



HF



TEL: +86-755- 3320-2398 FCC ID: YHLBLUSTUDIO50 Page Number : B1 of B1 Report Issued Date : May 24, 2013

Report No. : FG341702

Report Version : Rev. 01