Report No. :FA5O1206


## Appendix D. SAR Test Setup Photos





**Right Cheek** 

**Right Tilted** 






Left Cheek **Left Tilted** 

TEL: 86-755-8637-9589 / FAX: 86-755-8637-9595

Issued Date: Nov. 30, 2015 FCC ID: YHLBLUSTONEPLUS Page D1 of D2 Form version. : 150415






Report No.: FA5O1206

Front, Test Separation 10 mm

Back, Test Separation 10 mm



Top Side, Test Separation 10 mm



Bottom Side, Test Separation 10 mm



Left Side, Test Separation 10 mm



Right Side, Test Separation 10 mm

TEL: 86-755-8637-9589 / FAX: 86-755-8637-9595

FCC ID: YHLBLUSTONEPLUS

 $\begin{tabular}{ll} Issued Date: Nov. 30, 2015 \\ Page D2 of D2 & Form version. : 150415 \end{tabular}$