

Appendix B. Setup Photographs

<Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH32 Page Number : B1 of B2 Report Issued Date : Dec. 17, 2012

Report No.: FR2N2401B

Report Version : Rev. 01




<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH32 Page Number : B2 of B2
Report Issued Date : Dec. 17, 2012
Report Version : Rev. 01

Report No.: FR2N2401B