SPORTON INTERNATIONAL (KUNSHAN) INC.

Date: January 12, 2012

Cover Letter

SUBJECT: FCC document substitute for FCC ID: YHLACECCSPR

We are sorry that we have typo error for the issue date for below report:

FR1D1302A_R01_Part15C_CT Asia_Caracas Pro_Report_for BT EDR;

FG1D1302_R01_Part22H.24E_CT Asia_Caracas Pro_Appendix B;

FG1D1302_R01_Part22H.24E_CT Asia_Caracas Pro_Report;

FA1D1302_R01_FCC SAR_CT Asia_Caracas Pro_Report;

FA1D1302_R01_FCC SAR_CT Asia_Caracas Pro_Appendix A;

FA1D1302_R01_FCC SAR_CT Asia_Caracas Pro_Appendix B;

FA1D1302_R01_FCC SAR_CT Asia_Caracas Pro_Appendix C;

The issue date should be revised from Jan. 10, 2011 to Jan. 10, 2012.

And please substitute use below documents to FCC database.

FR1D1302A_R01_Part15C_CT Asia_Caracas Pro_Report_for BT EDR Rev1;

FG1D1302_R01_Part22H.24E_CT Asia_Caracas Pro_Appendix B Rev1;

FG1D1302_R01_Part22H.24E_CT Asia_Caracas Pro_Report Rev1;

FA1D1302_R01_FCC SAR_CT Asia_Caracas Pro_Report Rev1;

FA1D1302_R01_FCC SAR_CT Asia_Caracas Pro_Appendix A Rev1;

FA1D1302 R01 FCC SAR CT Asia Caracas Pro Appendix B Rev1;

FA1D1302_R01_FCC SAR_CT Asia_Caracas Pro_Appendix C Rev1;

Should you have any questions or comments regarding this matter, please have my best attention.

Best Regards

Michael Lin

SPORTON INTERNATIONAL (KUNSHAN) INC

Tel: +86-512-5790-0158 Fax: +86-512-5790-0958

Mail: Michael@Sporton.com.tw

Michael Lin