



Report No. : FA360409

Appendix D. Test Setup Photos



Right Cheek

Right Tilted




Left Cheek Left Tilted

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSAMBATV Page Number : D1 of D2
Report Issued Date : Jul. 03, 2013
Report Version : Rev. 01



FCC SAR Test Report





Report No. : FA360409

Front of the DUT with Phantom 1.5 cm Gap

Back of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSAMBATV Page Number : D2 of D2 Report Issued Date: Jul. 03, 2013

Report Version : Rev. 01