

Report No. : FA342204

Appendix D. SAR Test Setup Photos





Right Cheek

Right Tilted





Left Cheek

Left Tilted

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASHMUSIC Page Number : D1 of D2
Report Issued Date : May 27, 2013

Report Version : Rev. 01





Front of the DUT with Phantom 1 cm Gap




Report No. : FA342204

Back of the DUT with Phantom 1 cm Gap



Right Side of the DUT with Phantom 1 cm Gap



Left of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASHMUSIC Page Number : D2 of D2 Report Issued Date: May 27, 2013 Report Version : Rev. 01