
Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



Mode 4



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIOTCH Page Number : A1 of A3
Report Issued Date : May 13, 2016
Report Version : Rev. 01


Report No.: FC640701

Report Template No.: BU5-FC15B Version 1.3


<Radiated Emission>

Mode 1

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIOTCH Page Number : A2 of A3
Report Issued Date : May 13, 2016
Report Version : Rev. 01

Report No.: FC640701

Report Template No.: BU5-FC15B Version 1.3




Mode 4









SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIOTCH

: A3 of A3 Page Number Report Issued Date: May 13, 2016 : Rev. 01 Report Version

Report Template No.: BU5-FC15B Version 1.3

Report No.: FC640701