
Appendix C. Setup Photographs


<Radiated Emission>

Y Plane for 22H

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUNEOEMINI Page Number : C1 of C3
Report Issued Date : Apr. 14, 2016
Report Version : Rev. 01


Report No.: FG621907

Report Template No.: BU5-FG22/24/27/90 Version 1.1


Report No.: FG621907

X Plane for 24E

LF



HF




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUNEOEMINI Page Number : C2 of C3
Report Issued Date : Apr. 14, 2016
Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27/90 Version 1.1


Report No.: FG621907

Z Plane for 27L

LF



HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUNEOEMINI Page Number : C3 of C3
Report Issued Date : Apr. 14, 2016
Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27/90 Version 1.1