



Report No.: FA3D0901


## Appendix D. Test Setup Photos






Right Cheek

**Right Tilted** 





Left Cheek

Left Tilted

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLULIFEPUREM Page Number : D1 of D2
Report Issued Date : Jan. 06, 2014
Report Version : Rev. 01





Report No.: FA3D0901

Front of the DUT with Phantom 1 cm Gap

Back of the DUT with Phantom 1 cm Gap



Right Side of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLULIFEPUREM Page Number : D2 of D2 Report Issued Date: Jan. 06, 2014 Report Version : Rev. 01