

Appendix B. Setup Photographs

<Conducted Emission>





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : B1 of B2
Report Issued Date : Aug. 21, 2017
Report Version : Rev. 01

Report No.: FR762701A

Report Template No.: BU5-FR15CBT Version 2.0




Report No. : FR762701A

<Radiated Emission>

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : B2 of B2
Report Issued Date : Aug. 21, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 2.0