

Report No.: HA090827-03B

Appendix D. Product Photos



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSAMBAQ Page Number : D1 of D1
Report Issued Date : Aug.17, 2011
Report Version : Rev. 01




Appendix E. Test Setup Photos



Front View



Left Side View



Right Side View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSAMBAQ Page Number : E1 of E1
Report Issued Date : Aug.17, 2011
Report Version : Rev. 01

Report No.: HA090827-03B