




Page Number : A106 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




Page Number : A107 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




Page Number : A108 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




Page Number : A109 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




Page Number : A110 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5



Page Number : A111 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




Page Number : A112 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




Page Number : A113 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5

Conducted Spurious Emission




SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTXLLTE Page Number : A114 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTXLLTE Page Number : A115 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




Page Number : A116 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




Page Number : A117 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTXLLTE Page Number : A118 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




Page Number : A119 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




Page Number : A120 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTXLLTE Page Number : A121 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




Page Number : A122 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5



Page Number : A123 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTXLLTE Page Number : A124 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTXLLTE Page Number : A125 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5