

Report No.: FA1D0107

## Appendix D. Product Photos




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJLITE Page Number : D1 of D1
Report Issued Date : Dec. 09, 2011
Report Version : Rev. 01



## Report No.: FA1D0107

## Appendix E. Test Setup Photos



**Right Cheek** 









**Left Tilted** 



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJLITE Page Number : E1 of E1
Report Issued Date : Dec. 09, 2011
Report Version : Rev. 01