# Appendix A. Setup Photographs

## <Conducted Emission>

#### Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH35II Page Number : A1 of A2
Report Issued Date : Nov. 18, 2014


Report No.: FR4O0904B

Report Version : Rev. 01




## Y Plane

LF



#### HF



## SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH35II

: A2 of A2 Page Number Report Issued Date: Nov. 18, 2014

Report No.: FR4O0904B

Report Version : Rev. 01