Report No. :FA651207


## Appendix D. SAR Test Setup Photos





**Right Cheek** 

**Right Tilted** 





Left Cheek **Left Tilted** 

TEL: 86-755-8637-9589 / FAX: 86-755-8637-9595

Issued Date: Jun. 20, 2016 Form version. : 160427 FCC ID: YHLBLUSTDC88LTE Page D1 of D2



Report No.: FA651207



Front, Test Separation 10 mm


Back, Test Separation 10 mm




Left Side, Test Separation 10 mm



Right Side, Test Separation 10 mm



Top Side, Test Separation 10 mm



Bottom Side, Test Separation 10 mm

Page D2 of D2

TEL: 86-755-8637-9589 / FAX: 86-755-8637-9595

FCC ID: YHLBLUSTDC88LTE

Issued Date : Jun. 20, 2016 Form version. : 160427