



## Appendix B. Setup Photographs

## <Conducted Emission>

Mode 1



Front View



Rear View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSAMBMN Page Number : B1 of B4
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01

Report No.: FR090827





Report No. : FR090827



Side View

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSAMBMN Page Number : B2 of B4
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01





Report No. : FR090827

## <Radiated Emission>



Front View



Rear View


SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSAMBMN Page Number : B3 of B4
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01





Report No.: FR090827



Remote View

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSAMBMN Page Number : B4 of B4
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01