


## Appendix D. Setup Photographs

## <Conducted Emission>





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUS1 Page Number : D1 of D2
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01

Report No.: FR761305B


Report Template No.: BU5-FR15CBT4.1 Version 2.0




## <Radiated Emission>

## **Z** Plane

LF



HF



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUS1 Page Number : D2 of D2
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.1 Version 2.0

Report No.: FR761305B