
Report No. :FA591106


Appendix D. SAR Test Setup Photos






Right Cheek

Right Tilted






Left Cheek **Left Tilted**

TEL: 86-755-8637-9589 / FAX: 86-755-8637-9595

Issued Date: Nov. 16, 2015 Page D1 of D2 Form version. : 150415 FCC ID: YHLBLUDASHXLTE




Report No.: FA591106


Front, Test Separation 10 mm

hadantanlant


Back, Test Separation 10 mm



Top Side, Test Separation 10 mm



Bottom Side, Test Separation 10 mm



Left Side, Test Separation 10 mm

TEL: 86-755-8637-9589 / FAX: 86-755-8637-9595

Issued Date: Nov. 16, 2015 Form version. : 150415 FCC ID: YHLBLUDASHXLTE Page D2 of D2