

Report No.: FA090824

Appendix D. Product Photos









SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : D1 of D1
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01



Report No.: FA090824

Appendix E. **Test Setup Photos**



Right Cheek



Right Tilted



Left Cheek



Left Tilted



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ

Page Number : E1 of E1 Report Issued Date: Sep. 27, 2010 Report Version : Rev. 01