
Appendix A. Setup Photographs

<Conducted Emission>

Mode 2





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVOX Page Number : A1 of A4
Report Issued Date : Nov. 29, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No.: FC7O3102

CC Test Report No. : FC7O3102

Mode 5





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCCID: YHLBLUVIVOX Page Number : A2 of A4
Report Issued Date : Nov. 29, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3


<Radiated Emission>

Mode 3

LF



HF



Sporton International (Shenzhen) Inc.


TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCCID: YHLBLUVIVOX Page Number : A3 of A4
Report Issued Date : Nov. 29, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3


Report No.: FC7O3102

Mode 5

LF



ΗF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCCID: YHLBLUVIVOX Page Number : A4 of A4
Report Issued Date : Nov. 29, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No.: FC7O3102