


## Appendix B. Setup Photographs

## <Radiated Emission>

E1-Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPEEDII Page Number : B1 of B2
Report Issued Date : Jan. 25, 2013
Report Version : Rev. 01


Report No.: FG2D0601





E2-Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPEEDII Page Number : B2 of B2
Report Issued Date : Jan. 25, 2013
Report Version : Rev. 01

Report No.: FG2D0601