Report No. :FA5O0914

## Appendix D. SAR Test Setup Photos





**Right Cheek** 

**Right Tilted** 







Left Cheek **Left Tilted** 

TEL: 86-755-8637-9589 / FAX: 86-755-8637-9595

Issued Date : Nov. 27, 2015 Page D1 of D2 Form version. : 150415 FCC ID: YHLBLULIFEONE54




Front, Test Separation 10 mm




Report No.: FA5O0914


Back, Test Separation 10 mm




Top Side, Test Separation 10 mm



Bottom Side, Test Separation 10 mm



Left Side, Test Separation 10 mm



Right Side, Test Separation 10 mm

TEL: 86-755-8637-9589 / FAX: 86-755-8637-9595

Issued Date: Nov. 27, 2015 Form version. : 150415 FCC ID: YHLBLULIFEONE54 Page D2 of D2