Appendix B. Setup Photographs

<Conducted Emission>



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULIFEVIEW8 Page Number : B1 of B2
Report Issued Date : Jan. 04, 2015

Report No.: FR472201B


Report Version : Rev. 01




<Radiated Emission>

Z Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULIFEVIEW8 Page Number : B2 of B2
Report Issued Date : Jan. 04, 2015

Report No. : FR472201B

Report Version : Rev. 01