

Report No.: FA1D0806

Appendix D. Product Photos




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO Page Number : D1 of D1
Report Issued Date : Jan. 06, 2012
Report Version : Rev. 01



Report No.: FA1D0806

Appendix E. Test Setup Photos






Right Cheek







Left Cheek


Left Tilted

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO Page Number : E1 of E2 Report Issued Date: Jan. 06, 2012 : Rev. 01

Report Version



Front of the DUT with Phantom 1 cm Gap



Report No.: FA1D0806

Back of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap



Right Side of the DUT with Phantom 1 cm Gap



Left Side of the DUT with Phantom 1 cm Gap

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO Page Number : E2 of E2
Report Issued Date : Jan. 06, 2012
Report Version : Rev. 01