

3. Internal Photograph of EUT

Brand Name: BLU; Model Name: STUDIO C 5+5 LTE

Report No.: EP571406



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTC55LTE Page Number : 12 of 30
Report Issued Date : Sep. 08, 2015
Report Version : Rev. 01





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTC55LTE Page Number : 13 of 30
Report Issued Date : Sep. 08, 2015
Report Version : Rev. 01





Report No.: EP571406



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTC55LTE


: 14 of 30 Page Number Report Issued Date : Sep. 08, 2015 Report Version : Rev. 01





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTC55LTE Page Number : 15 of 30
Report Issued Date : Sep. 08, 2015
Report Version : Rev. 01






TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTC55LTE Page Number : 16 of 30
Report Issued Date : Sep. 08, 2015
Report Version : Rev. 01



Report No.: EP571406



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTC55LTE Page Number : 17 of 30 Report Issued Date : Sep. 08, 2015




Report No.: EP571406



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTC55LTE Page Number : 18 of 30 Report Issued Date : Sep. 08, 2015 Report Version : Rev. 01




Report No.: EP571406



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTC55LTE Page Number : 19 of 30 Report Issued Date : Sep. 08, 2015 Report Version : Rev. 01



Report No.: EP571406



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTC55LTE Page Number : 20 of 30 Report Issued Date : Sep. 08, 2015

Report No.: EP571406



SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTC55LTE

: 21 of 30 Page Number

Report Issued Date : Sep. 08, 2015




Report No.: EP571406




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTC55LTE Page Number : 22 of 30 Report Issued Date : Sep. 08, 2015

Report No.: EP571406



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTC55LTE Page Number : 23 of 30
Report Issued Date : Sep. 08, 2015
Report Version : Rev. 01


Report No.: EP571406



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTC55LTE Page Number : 24 of 30
Report Issued Date : Sep. 08, 2015
Report Version : Rev. 01




Report No.: EP571406




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTC55LTE Page Number : 25 of 30 Report Issued Date : Sep. 08, 2015 : Rev. 01 Report Version

Report No.: EP571406




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTC55LTE Page Number : 26 of 30
Report Issued Date : Sep. 08, 2015
Report Version : Rev. 01

Report No.: EP571406




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTC55LTE Page Number : 27 of 30
Report Issued Date : Sep. 08, 2015
Report Version : Rev. 01

Report No.: EP571406




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTC55LTE Page Number : 28 of 30
Report Issued Date : Sep. 08, 2015
Report Version : Rev. 01

graphs of EUT Report No.: EP571406



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTC55LTE Page Number : 29 of 30
Report Issued Date : Sep. 08, 2015
Report Version : Rev. 01

Report No.: EP571406



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTC55LTE Page Number : 30 of 30
Report Issued Date : Sep. 08, 2015
Report Version : Rev. 01