


Appendix D. Product Photos







TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUELITE Page Number : D1 of D2
Report Issued Date : Jun. 14, 2012
Report Version : Rev. 01

Report No.: FA250202



Report No.: FA250202

Antenna location:





Antenna	Length	Width
WWAN Antenna (Tx / Rx)	2.6 cm	0.5 cm
Bluetooth & WLAN Antenna (Tx / Rx)	4.9 cm	0.8 cm
GPS Antenna (Rx)	2.8 cm	1.5 cm


SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUELITE Page Number : D2 of D2
Report Issued Date : Jun. 14, 2012
Report Version : Rev. 01



Report No.: FA250202

Appendix E. Test Setup Photos




Right Cheek


Right Tilted







Left Tilted



Front of the DUT with Phantom 1 cm Gap




Back of the DUT with Phantom 1 cm Gap


SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUELITE Page Number : E1 of E2
Report Issued Date : Jun. 14, 2012
Report Version : Rev. 01





Front of the DUT with Phantom 1 cm Gap (with Earphone)




Report No.: FA250202

Back of the DUT with Phantom 1 cm Gap (with Earphone)



Left Side of the DUT with Phantom 1 cm Gap



Right Side of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUELITE

Page Number : E2 of E2 Report Issued Date: Jun. 14, 2012 Report Version : Rev. 01