## 3. Internal Photograph of EUT


Brand Name: BLU; Model Name: Dash 5.0


**Report No.: EP381615** 



TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH50 Page Number : 11 of 25
Report Issued Date : Sep. 19, 2013

Report Version : Rev. 01





TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH50 Page Number : 12 of 25
Report Issued Date : Sep. 19, 2013
Report Version : Rev. 01






TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH50 Page Number : 13 of 25
Report Issued Date : Sep. 19, 2013
Report Version : Rev. 01





TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH50 Page Number : 14 of 25
Report Issued Date : Sep. 19, 2013
Report Version : Rev. 01


**Report No.: EP381615** 



TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH50 Page Number : 15 of 25
Report Issued Date : Sep. 19, 2013
Report Version : Rev. 01




**Report No.: EP381615** 



TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH50

: 16 of 25 Page Number Report Issued Date : Sep. 19, 2013 Report Version : Rev. 01






TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH50 Page Number : 17 of 25
Report Issued Date : Sep. 19, 2013
Report Version : Rev. 01



Report No.: EP381615




TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH50

: 18 of 25 Page Number Report Issued Date : Sep. 19, 2013 Report Version : Rev. 01




Report No.: EP381615



TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH50

: 19 of 25 Page Number Report Issued Date : Sep. 19, 2013 Report Version : Rev. 01

**Report No.: EP381615** 




TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH50 Page Number : 20 of 25
Report Issued Date : Sep. 19, 2013
Report Version : Rev. 01

**Report No.: EP381615** 



TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH50 Page Number : 21 of 25
Report Issued Date : Sep. 19, 2013
Report Version : Rev. 01


**Report No.: EP381615** 



TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH50 Page Number : 22 of 25
Report Issued Date : Sep. 19, 2013
Report Version : Rev. 01




Report No.: EP381615



TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH50

: 23 of 25 Page Number Report Issued Date : Sep. 19, 2013 Report Version : Rev. 01



TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH50

: 24 of 25 Page Number Report Issued Date : Sep. 19, 2013

**Report No.: EP381615** 

Report Version : Rev. 01



TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH50

: 25 of 25 Page Number Report Issued Date : Sep. 19, 2013 Report Version : Rev. 01

Report No.: EP381615