

# Appendix B. Setup Photographs

## <Conducted Emission>

#### Mode 2



Mode 4



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIOII Page Number : B1 of B2
Report Issued Date : Feb. 06, 2013
Report Version : Rev. 01

**Report No. : FC311601** 





**Report No. : FC311601** 


### <Radiated Emission>

#### Mode 4

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIOII

: B2 of B2 Page Number Report Issued Date: Feb. 06, 2013 Report Version : Rev. 01