

Report No.: FC411002

# Appendix A. Setup Photographs

# <Conducted Emission>

### Mode 2



Mode 3



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD50SII Page Number : A1 of A2 Report Issued Date: Mar. 04, 2014 Report Version : Rev. 01







# <Radiated Emission>

### Mode 3

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD50SII Page Number : A2 of A2
Report Issued Date : Mar. 04, 2014
Report Version : Rev. 01

Report No.: FC411002