

Appendix E. Setup Photographs

<Conducted Emission>

Mode 1





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVOXL4 Page Number : E1 of E2
Report Issued Date : Sep. 28, 2018
Report Version : Rev. 01
Report Template No.: BU5-FR15CBLE Version 2.0

Report No.: FR883001B




<Radiated Emission>

X Plane

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVOXL4 Page Number : E2 of E2
Report Issued Date : Sep. 28, 2018
Report Version : Rev. 01

Report No.: FR883001B

Report Template No.: BU5-FR15CBLE Version 2.0