

Report No. : FA341702

Appendix D. Test Setup Photos





Right Cheek

Right Tilted





Left Cheek


Left Tilted

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO50 Page Number : D1 of D2
Report Issued Date : May 24, 2013

Report Version : Rev. 01







Report No. : FA341702

Front of the DUT with Phantom 1 cm Gap

Back of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap



Right Side of the DUT with Phantom 1 cm Gap



Left Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO50

: D2 of D2 Page Number Report Issued Date: May 24, 2013 Report Version : Rev. 01