Appendix D. SAR Test Setup Photos






Report No.: FA853112

Right Cheek

Right Tilted





Left Cheek Left Tilted

TEL: +86-755-8637-9589 / FAX: +86-755-8637-9595 Issued Date : Jun. 26, 2018 FCC ID: YHLBLUVIVOXIP Page D1 of D2 Form version. : 170509






Front, Test Separation 10 mm

Back, Test Separation 10 mm


Report No. : FA853112




Left Side, Test Separation 10 mm



Right Side, Test Separation 10 mm



Top Side, Test Separation 10 mm



Bottom Side, Test Separation 10 mm

Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 / FAX: +86-755-8637-9595

FCC ID: YHLBLUVIVOXIP

Issued Date Page D2 of D2

: Jun. 26, 2018 Form version. : 170509