## 3. Internal Photograph of EUT

Brand Name: BLU; Model Name: Life Pro

**Report No.: EP383001** 



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO



Report No.: EP383001



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO Page Number : 13 of 32 Report Issued Date : Sep. 24, 2013 Report Version : Rev. 01



Report No.: EP383001



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO

: 14 of 32 Page Number Report Issued Date : Sep. 24, 2013 Report Version : Rev. 01



Report No.: EP383001



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO

: 15 of 32 Page Number Report Issued Date : Sep. 24, 2013 Report Version : Rev. 01



Report No.: EP383001



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO

: 16 of 32 Page Number Report Issued Date : Sep. 24, 2013 Report Version : Rev. 01

Report No.: EP383001

IMEI:012345678910
Model:Life Pro
Part No.:L210a
Type:01
Type:D:YHLBLULIFEPRO 

Brand Name: BLU; Model Name: Life Pro

TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO

: 17 of 32 Page Number Report Issued Date : Sep. 24, 2013 Report Version : Rev. 01




Report No.: EP383001



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO

: 18 of 32 Page Number Report Issued Date : Sep. 24, 2013 Report Version : Rev. 01


Report No.: EP383001



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO Page Number : 19 of 32
Report Issued Date : Sep. 24, 2013
Report Version : Rev. 01




Report No.: EP383001



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO Page Number : 20 of 32 Report Issued Date : Sep. 24, 2013 Report Version : Rev. 01




Report No.: EP383001



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO Page Number : 21 of 32 Report Issued Date : Sep. 24, 2013 Report Version : Rev. 01

Report No.: EP383001



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO Page Number : 22 of 32
Report Issued Date : Sep. 24, 2013
Report Version : Rev. 01

Report No.: EP383001



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO Page Number : 23 of 32
Report Issued Date : Sep. 24, 2013
Report Version : Rev. 01




Report No.: EP383001



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO Page Number : 24 of 32
Report Issued Date : Sep. 24, 2013
Report Version : Rev. 01


Report No.: EP383001



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO Page Number : 25 of 32
Report Issued Date : Sep. 24, 2013
Report Version : Rev. 01




Report No.: EP383001



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO Page Number : 26 of 32 Report Issued Date : Sep. 24, 2013 Report Version : Rev. 01




Report No.: EP383001




TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO Page Number : 27 of 32 Report Issued Date : Sep. 24, 2013 Report Version : Rev. 01

Report No.: EP383001




TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO Page Number : 28 of 32
Report Issued Date : Sep. 24, 2013
Report Version : Rev. 01

Report No.: EP383001



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO Page Number : 29 of 32
Report Issued Date : Sep. 24, 2013
Report Version : Rev. 01


Report No.: EP383001



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO Page Number : 30 of 32
Report Issued Date : Sep. 24, 2013
Report Version : Rev. 01




Report No.: EP383001



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO

: 31 of 32 Page Number Report Issued Date : Sep. 24, 2013 Report Version : Rev. 01



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO Page Number : 32 of 32
Report Issued Date : Sep. 24, 2013
Report Version : Rev. 01