

**Report No.: FA181904** 

## Appendix D. Product Photos









SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUTATTOOMN Page Number : D1 of D2
Report Issued Date : Sep. 16, 2011
Report Version : Rev. 01



## **Antenna Location:**



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YHLBLUTATTOOMN Page Number : D2 of D2
Report Issued Date : Sep. 16, 2011
Report Version : Rev. 01

**Report No. : FA181904** 



## Report No. : FA181904

## Appendix E. Test Setup Photos





**Right Cheek** 

**Right Tilted** 







**Left Tilted** 



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUTATTOOMN Page Number : E1 of E1
Report Issued Date : Sep. 16, 2011
Report Version : Rev. 01