Federal Communications Commission Office of Engineering and Technology November 16, 2010

Re: FCC ID: YIB157S

FCC Registration No: 0017527912 Form 731 Confirmation No: EA175426 Correspondence Reference No: 39298

Subject: Request to change FCC ID number to YIBSEA157S

On the Form 731 referenced above I made an error on the product code. It should be SEA157S not 157S. All of the test report and the maintenance manual for the radio have YIBSEA157S as the FCC identifier. I apologize for the error and would like to get it corrected.

Please change the FCC ID number from YIB157S to YIBSEA157S on this application for type acceptance. Thank you.

Sincerely, Gary L. Kison Senior Engineering Technician Sea Com Corp. 7030 220th St. SW Mountlake Terrace, WA 98043 425-771-2181 x145

Fax: 425-771-2650