

HARSTON MILL, ROYSTON RD, CAMBRIDGE, CB22 7GG, UK

TELEPHONE: +44 (0) 1223 792 101 FAX: +44 (0) 1223 792 103 E-MAIL: info@enecsys.com

Declaration of conformity to antenna requirements of section 15.203

23rd August 2010

TRaC Global 100 Frobisher Business Park Leigh Sinton Road Malvern Worcestershire WR14 1BX UK

RE: Certification Application FCC ID: YIWDEREPEATER0001

To Whom It May Concern:

Please be advised that the Enecsys Limited uses non-standard antenna connectors for its double repeater, single repeater and gateway products. The non-standard antenna connectors are a RPSMA type. In using such non-standard antenna connector types Enecsys believes that is meets section 15.203 from the FCC.

Thank you for your attention to this matter.

Yours faithfully

Enecsys Limited

Dr Asim Mumtaz