WatchMate Vision XB9000 Device Labeling



103 Westhaven Drive, St. Mary's Bay PO Box 91164, Victoria Street West Auckland, New Zealand

> Phone: +64 (0)9 950 4848 Fax: +64 (0)9 950 4085

www.vespermarine.com

Version History

Version	Date	Comment
1	7 Oct 2012	First Release
2	10/09/12	FCC ID Correction
3	10/14/12	Vision Label Update

Copyright Notice

Copyright © 2012, Vesper Marine Ltd. All rights are reserved.

The information contained within this document is the copyright of Vesper Marine Ltd

No part of this document may be disclosed, reproduced or transmitted in any form, or by any means without the written permission of Vesper Marine Ltd. The term document extends to all forms of media in which information may be embodied.

Product Family Indentification

Products	WatchMate Vision
Trade Name	Vesper Marine Ltd
Model Numbers	XB9000
Power Supply	12-24V DC
AIS Frequency Range	161.500 – 162.025 MHz TX 156.025 – 162.025 MHz RX
AIS Transmit Power	33dBm (2W)
Modulation Technique	FM GMSK
Channel Spacing	25kHz
Temperature Range	-25 - +55 deg C
Intended Users	General Public
GPS Antenna	Internal patch antenna (with connection for optional external antenna)
WiFi	802.11 b/g
WiFi Antenna	SMT PCB
WiFi Power output	15dBm
Equipment type	Fixed (Not portable)
Enclosure	IPX7
Firmware Version	V5.06

For more details please refer to the user manual and website www.vespermarine.com

FCC Warning Text

The device and space set aside for labeling is deemed to small to fit the complete two part warning message as required by Section 15.19.

In accordance with Section 15.19 (a) 5 this text has been placed in the Warnings Section of each products user manual.

XB9000



Input: 12-24VDC 2A max, 6W nom Compass safe distance: 0.65m (2.2ft)

NMEA 2000 LEN: 2

(€ 0168 ①

BSH: 46162/4322190/12

USCG: 165.156/19/0

FCC ID: YJDVESPXB9000

S/N: JZ62158 Model: XB9000

For customers in the USA: This device must be programmed with data corresponding to the vessel on which it will be installed. Programming must be carried out by a Vesper Marine dealer. The included instructions contain information on how to verify the correct programming.

WARNING: It is a violation of the rules of the Federal Communications Commission to input an MMSI that has not been properly assigned to the end user, or to otherwise input any inaccurate data in this device.

WatchMate Vision (XB9000) Label



WatchMate Vision (XB9000) Rear View Showing Label Location (actual label is shown above)