Test report No. : 30CE0008-YK-01-D-R1

 Page
 : 11 of 20

 Issued date
 : July 23, 2010

 Revised date
 : September 15, 2010

 FCC ID
 : YK4-JW9-85579-00

APPENDIX 1: Photographs of test setup

Radiated Emission



Photo 1



Photo 2

UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 30CE0008-YK-01-D-R1

 Page
 : 12 of 20

 Issued date
 : July 23, 2010

 Revised date
 : September 15, 2010

 FCC ID
 : YK4-JW9-85579-00

Worst case position (Horizontal: X-axis/Vertical: Y-axis)

X-axis



Y-axis



Z-axis



Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124