Test report No. : 30CE0008-YK-01-B-R1

 Page
 : 12 of 26

 Issued date
 : July 23, 2010

 Revised date
 : September 15, 2010

 FCC ID
 : YK4-JW9-85560-00

APPENDIX 1: Photographs of test setup

Conducted Emission



Photo 1




Photo 2

UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 30CE0008-YK-01-B-R1

 Page
 : 13 of 26

 Issued date
 : July 23, 2010

 Revised date
 : September 15, 2010

 FCC ID
 : YK4-JW9-85560-00

Radiated Emission



Photo 1




Photo 2

UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124