

ACTION

360 DEGREE SPIND G TUMBLING ACTION

MARNING: CHOKING HAZARD
TOY CONTAINS SMALL PARTS, NOT FOR CHILDREN UNDER 3 YEARS.

MINDSCOPE

360 DEC





COLOR:BLUE FREQUENCY:49MHZ ITEM #: MOON

Product and color may vary.
Made in Shantou, Guangdong, China
BATCH NUMBER: 050513
DATE OF MANUFACTURE: 05/05/2013

CAUTION


- Hemove our patients and replace with new patients as sure to insert batteries correctly according to (+) and (-) symbols located the battery compariment.
- Be sure to insert batteries correctly with adult supervision and supervision the low and batters provide huges inclined on the low and batters provide huges inclined on the low and batters are provided by the low and by the lo
- Do not mix o'd and new batterle
- Do not mix a kaline, standard (carbo-zmé), or rechargeab (nickel-cadmium) batteries.
- Rechargeable batteries are to be removed from the toy before bein charged.
- . Non-rechargeable batteries are not to be recharged
- . Do not dispuse of batteries in fire
- Batteries should be recycled or disposed of as per state and local guidelines
- Hechargeable batteries are only to be charged under adult supervision
- Only batteries of the same equivalent type as recommended are to be used.
- The supply terminals are not to be short-circuited
- · Always remove weak or dead batteries from the produ
- Remove batteries if the product will be stored for an extende pariod of time.
- . Please retain these instructions for
- For best results use alkaline betienes

Total of 6 AA 1.5V Batteries (Not Included)





Vehicle Requires: 4 AA 1.5V Batteries (Not Included)



Remote Control Requires: 2 AA 1.5V Batteries (Not Included)

This device complies with Part 15 of the FCC rules. Operation is subject to the following two conditions:

(1) this device may not cause harmful interference and

(2) this device must accept any interference received, including interference that may cause undesired operation.

Warning: Changes or modifications to this unit not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

NOTE: This sendement has been tested and found to comply with limits for a Cass Beignia device, pursuant to 7 that 15 of the FCC Rules.

These limits are depined to provide read broaded protection. A paint harmful interference in a reademial installation. This representation of the provided provided

However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference.

by one or more of the following marrys

- by one or more or are rollowing measures.
- · Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.