

Client: Alarm.com Model/HVIN: ADC-470L Standards: FCC 15.247/IC RSS-247 ID's: YL6-143470L/9111A-143470L Report #: 2016204DTS

Appendix L: External Photographs




Photograph 6: Module Top View

Client: Alarm.com Model/HVIN: ADC-470L Standards: FCC 15.247/IC RSS-247 ID's: YL6-143470L/9111A-143470L Report #: 2016204DTS




Photograph 7: Module Bottom View

Client: Alarm.com Model/HVIN: ADC-470L Standards: FCC 15.247/IC RSS-247 ID's: YL6-143470L/9111A-143470L Report #: 2016204DTS



Photograph 8: Module Top View - No Shields

Client: Alarm.com Model/HVIN: ADC-470L Standards: FCC 15.247/IC RSS-247 ID's: YL6-143470L/9111A-143470L Report #: 2016204DTS



Photograph 9: Module Bottom View - No Shields