

Client: Alarm.com Model/HVIN: ADC-470L Standards: FCC 15.247/IC RSS-247 ID's: YL6-143470L/9111A-143470L Report #: 2016204DTS

Appendix M: Internal Photographs




Photograph 10: Module Top View

Client: Alarm.com Model/HVIN: ADC-470L Standards: FCC 15.247/IC RSS-247 ID's: YL6-143470L/9111A-143470L Report #: 2016204DTS



Photograph 11: Module Bottom View

Client: Alarm.com Model/HVIN: ADC-470L Standards: FCC 15.247/IC RSS-247 ID's: YL6-143470L/9111A-143470L Report #: 2016204DTS



Photograph 12: Module Top View – No Shields

Client: Alarm.com Model/HVIN: ADC-470L Standards: FCC 15.247/IC RSS-247 ID's: YL6-143470L/9111A-143470L Report #: 2016204DTS



Photograph 13: Module Bottom View – No Shields